SEGA®

C2 RESET INSTALL

1. ADD FRESH SOLDER TO THE TWO POINTS SHOWN IN RED.



2. SOLDER THE INCLUDED CABLE AS SHOWN (WIRE COLOUR IS REVERSIBLE).



3. CONNECT RESET CABLE TO DIP PCB BEFFORE CONNECTING TO MULTI.